




# SOUND ABSORPTION AREA FOR OBJECT

Measured and evaluated according to ISO 354 and ISO 20189

|                   |                       |         |        |
|-------------------|-----------------------|---------|--------|
| <b>Client:</b>    | Boom Interior         |         |        |
| <b>Object:</b>    | Xrozz Absorption Plus |         |        |
| <b>Size [mm]:</b> | w = 600               | h = 800 | d = 50 |

| Octave band (Hz)             | Equivalent sound absorption area / unit (m <sup>2</sup> Sabine) |
|------------------------------|---|
| 63                           | 0.07  |
| 125                          | 0.16  |
| 250                          | 0.38  |
| 500                          | 0.6   |
| 1000                         | 0.81  |
| 2000                         | 0.87  |
| 4000                         | 0.99  |
| <b>N<sub>10</sub> = 16.7</b> |   |



|                                  |                       |
|----------------------------------|-----------------------|
| <b>ORIGINAL TEST REPORT</b>      | <b>DATE OF REPORT</b> |
| Akustikverkstan report 21-720-M1 | 2021-06-23            |

